


TUNVALVE




In the event of an overflow discharge, the cause should be rectified immediately.

For Cisterns with a side overflow, fitting FTC1AWH is required

McAlpine & Co Ltd.
Kelvin Ave,
Hillington
Glasgow, G52 4LF
www.mcalpineplumbing.com

TUNVALVE




In the event of an overflow discharge, the cause should be rectified immediately.

For Cisterns with a side overflow, fitting FTC1AWH is required

McAlpine & Co Ltd.
Kelvin Ave,
Hillington
Glasgow, G52 4LF
www.mcalpineplumbing.com

TUNVALVE



In the event of an overflow discharge, the cause should be rectified immediately.

For Cisterns with a side overflow, fitting FTC1AWH is required

McAlpine & Co Ltd.
Kelvin Ave,
Hillington
Glasgow, G52 4LF
www.mcalpineplumbing.com